



---

# Smoke and Dye Testing Summary

---

## High Level Sewershed

### Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-188	Smoke	7/22/2009	ADS/TM	S13AA_026MH	Dry	Yes	997.80

### Isolated Pipes

Pipe ID	Upstream MH	Downstream MH	Length (ft)	Diameter (In)
S13CC_023G1	S13CC_023MH	S13AA_022MH	103.794	8
S13AA_022G1	S13AA_022MH	S13AA_026MH	314.8	8
S13AA_026G1	S13AA_026MH	S13AA_014MH	282.556	8
S13AA_014G1	S13AA_014MH	S15AA_010MH	217.904	8
S15AA_010G1	S15AA_010MH	S15AA_025MH	78.7507	8

### Observations & Photos

**Obs\_ID** S1028-188-OB01

**Address** 2727 Riggs Ave

**Status** Private

**Source** Service Lateral

**Location** Paved concrete

**Nearest MH** S13AA\_014MH

**Comments** Smoke from service lateral under paved concrete in back yard. 2727 Riggs Ave.



**Picture** \S1028-188-OB01-P01.jpg

**Comments** Back of house, 2727 Riggs Ave.

**Obs\_ID** S1028-188-OB02

**Address** 2731 Riggs Ave

**Status** Private

**Source** Cleanout

**Location** Yard - back

**Nearest MH** S13AA\_014MH

**Comments** Smoke from above-grade cleanout (missing cap) in back yard. 2731 Riggs Ave.



**Picture** \S1028-188-OB02-P01.jpg

**Comments** Back of house, 2731 Riggs Ave.

---

# Smoke and Dye Testing Summary

---

## High Level Sewershed

### Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-188	Smoke	7/22/2009	ADS/TM	S13AA_026MH	Dry	Yes	997.80

**Obs\_ID** S1028-188-OB03

**Address** 1006 Dukeland St

**Status** Private

**Source** Cleanout

**Location** Paved concrete

**Nearest MH** S13AA\_026MH

**Comments** Smoke from above-grade cleanout (missing cap) in paved concrete in back yard. 1006 Dukeland St.



**Picture** \S1028-188-OB03-P01.jpg

**Comments** Back of house, 1006 Dukeland St.

**Obs\_ID** S1028-188-OB04

**Address** 2743 Riggs Ave

**Status** Private

**Source** Service Lateral

**Location** Paved concrete

**Nearest MH** S13AA\_014MH

**Comments** Smoke from service lateral under paved concrete in back yard. 2743 Riggs Ave.



**Picture** \S1028-188-OB04-P02.jpg

**Comments** Paved concrete behind house, 2743 Riggs Ave.

**Obs\_ID** S1028-188-OB04

**Address** 2743 Riggs Ave

**Status** Private

**Source** Service Lateral

**Location** Paved concrete

**Nearest MH** S13AA\_014MH

**Comments** Smoke from service lateral under paved concrete in back yard. 2743 Riggs Ave.



**Picture** \S1028-188-OB04-P01.jpg

**Comments** Back of house, 2743 Riggs Ave.

**Obs\_ID** S1028-188-OB05

**Address** 2743 Riggs Ave.

**Status** Private

**Source** Service Lateral

**Location** Yard - back

**Nearest MH** S13AA\_014MH

**Comments** Smoke from service lateral in back yard at retaining wall. 2743 Riggs Ave.



**Picture** \S1028-188-OB05-P01.jpg

**Comments** Back of house (flag in background), 2743 Riggs Ave.



---

# Smoke and Dye Testing Summary

---

## High Level Sewershed

### Run Summary

Test ID	Test Type	Date Inspected	Company / Super.	Blower MH	Ground Condition	Notification Made?	Total Length
S1028-188	Smoke	7/22/2009	ADS/TM	S13AA_026MH	Dry	Yes	997.80

**Obs\_ID** S1028-188-OB05

**Address** 2743 Riggs Ave.

**Status** Private

**Source** Service Lateral

**Location** Yard - back

**Nearest MH** S13AA\_014MH

**Comments** Smoke from service lateral in back yard at retaining wall. 2743 Riggs Ave.



**Picture** \S1028-188-OB05-P02.jpg

**Comments** Back yard, 2743 Riggs Ave.